



Ball Screw Lathe Video Instructions

We have videos on our website and our YouTube channel that show you how to mount the limit switches, how to mount the optical encoder, and how to check the signal from the limit switches and the encoder on your new ball screw lathe.

Sherline Video Web Page Links

1. Sherline Demonstration Videos

<https://www.sherline.com/sherline-videos/demonstration-videos/>

2. Sherline Instructional Videos

<https://www.sherline.com/sherline-videos/instructional-videos/>

3. Sherline/MASSO Instructional Videos

<https://www.sherline.com/sherline-videos/masso-videos/>

Direct YouTube Links

1. *Assembling Your Ball Screw Lathe*

https://youtu.be/TmfHy_Oabns

2. *Adjusting the Gibs on the Ball Screw Lathe*

<https://youtu.be/MGJk6ufV-xA>

3. *Installing Limit Swithes on the Ball Screw Lathe*

<https://youtu.be/XOo8dp9motc>

4. *Connecting MASSO to the Ball Screw Lathe*

https://youtu.be/A7T6z54y_SI

5. *Setting up Your New Sherline CNC Controller*

<https://youtu.be/PFPxKcHfZE8>

6. *Installing the Optical Encoder*

<https://youtu.be/p3kM3MEO1-w>

7. *Setting up the Optical Encoder*

<https://youtu.be/ynfJ38QLMoE>

Visit our YouTube channel to see all the great how-to videos. <https://www.youtube.com/c/sherlineproducts>

Thank you,
Sherline Products Inc.

